

# FOR MITIGATING DAMAGE IN CONCRETE DUE TO MATERIALS DEFICIENCIES

# Toy S. Poole

- Education:
  - BS Chemistry, PhD Zoology
- ▶ 32 y Corps of Engineers.
  - Retired 2010
  - Live in Austin, Texas
- Currently employed:
  - CTL Group
  - Consulting with Corps of Engineers
- ASTM since 1985
  - Committees C1 (cement) and C9 (concrete)
  - Board of Directors



# Background

- ▶ R&D → Standards → Application
- Much progress starting in the early 20<sup>th</sup> century
- Still gaps in standards that continue to cause problems
- Process of filling these gaps seems to have stalled in some cases
- Objective of presentation is to explore some of these and cogitate on causes



# Background

- Early History (modern era)
- Standards
  - ASTM C1 1902
  - ASTM C9 1914
  - AASHTO 1914
  - ACI ????
- MRD stds >1930



Bellafontaine, OH - 1891



#### **Critical Points**

- Determination of Specification Limits
- Field Service Records
- Precision of Test Methods
- Sampling of Materials



# **Origin of Specification Limits**

- Field-Service Records
- Lab test results
- Origin often unknown
  - Inadequate or non-existent historical records.



#### Field Service Records

- Analysis of old structures and comparison with new construction
  - Similar materials
  - Similar exposures
  - Sufficient age
  - Availability of "as builts"
- Conditions rarely met



#### Poor Precision of Test Methods

- Common in concrete mtls TM's
- Largely ignored
- Many problems in acceptance testing \$\$\$\$
- C78 (flex beam) good example





# Sampling of Materials

- Acceptance often on manufacturers certification (mill certificate)
  - Typically based on averaging
- User sampling is often by a single grab sample
- Significant variability in product stream
  - Aggregates spatial variation in quarry
  - Manufactured variation in raw materials, processes
- Result: What you test may not be what you get

# Examples

- Instability of aggregate to F/T cycles
- Air Entraining to mitigate F/T damage
- Alkali-aggregate Reaction
- Variation in coal fly ash



# Damage to Aggregate – Freezing and Thawing

- D-cracking (durability cracking)
- 9% expansion of freezing water in confined space
- Depends strongly on microstructure of rock
  - Coarse pore structure usually drains no damage
  - Fine pore structure holds water damage



# D Cracking – Concrete Pavements





>Usually with sedimentary-rock aggregates

>Usually associated with joints in pavement



# **Acceptance-Testing Problems**

- High level of uncertainty in test methods
- Owner vs Producer disputes common
- False rejections costly to contractors
- False acceptance costly to owners
- Sampling major issue



# ASTM C88 (1931) – "Sulfate Soundness Test"

- Wetting & drying
- simulation of freezing and thawing – changes in salt crystallization
- Metric is mass loss due to fracturing of rock





#### C88 Continued

- Short duration test
- Simple to execute
- Relatively cheap
- Poor precision
- Very aggressive test
- Origin of specification limits unknown
- A replacement test is needed



# ASTM C666 (1971) - Rapid Freezing and Thawing

- Simulates actual freezing and thawing conditions
- Laboratory fabricated concrete tests specimens or field cores
- Two alternatives (user selected)
  - Freeze and thaw in water (Procedure A)
  - Freeze in air, thaw in water (Procedure B)
- Metrics
  - Changes in modulus
  - Length Change
  - Mass Loss



# C666 Testing





#### C666 Continued

- Precision information incomplete
- Disagreement on interpretation of results
- ▶ Long test period (2 5 months)
- Expensive
- Validation difficult
- Needs a major review



# Air Entrainment: Mitigate F/T Damage to Cement Paste

- We know how to effectively mitigate damage just don't always do it
- Damage mechanism is same as in D-Cracking
  - But in cement paste (not aggregate)
- Mitigated by air entrainment





# Air Entraining

- Basic mechanism: small air bubble in cement paste provides a pressure relief system for water expansion immediately before freezing Discovered in 1940's
- Amount, size and spacing of air voids are critical
- Relatively delicate process to control



# Air Entraining Problems







# Deficiencies in Air – Early Damage








# Deficiencies in Air – Later Damage







### Construction Practice – Total Air






#### Failures: Whose Fault?

- Spec's
  - Limits on total air in front of the paver
  - No limits on total air after consolidation
  - No consideration for void size and spacing
- Compliance with specification does not insure performance
- Loss of air occurs during consolidation



# Problem – Loss of Air during consolidation





# Alkali-Aggregate Reaction

- Mineral components of some aggregates unstable at very high pH
  - Sodium and potassium salts causes high pH
- Forms expansive compounds within aggregate particle
- Resulting tensile forces crack concrete
- Relatively slow and long lasting



# Distressed Aggregate Particles







# Forms of AAR Presentation



Ft. Campbell, KY – Sub-cracking expansion



Carters Dam, GA – aggregate variation



#### AAR – General Problem

- Basically understand the reaction mechanisms
- Basically struggle to accurately determine
  - If the reaction will actually occur
  - When and if damage will occur
  - Whether mitigation will be effective
  - The long-term prognosis of the phenomenon



#### **Standards**

- Test methods expansion of laboratory specimens
- Test methods may not simulate actual service conditions all that well
- Validation against field conditions is difficult
- Testing suffers
  - Poor test method precision
  - Weak sampling schemes particularly sedimentary rock quarries



# Standard Testing

- Considerable ongoing work on test method revision
  - New concepts
  - Improvement in precision
- Sampling continues to be a problem
  - Variation in product streams can be significant and undetected



# Variability in Coal Fly Ash

- Coal Fly Ash
  - Has become an important part of concrete practice
- Variability
  - Common issue
  - Significant impacts during construction



#### **Fundamental Problem**

- Coal power plants have major concern
  - Environmental issues
  - Efficiency of energy extraction from coal
  - Economical coal supplies = variation
- Quality of fly ash is not a high priority





# Fly Ash Storage Failure






# Variable fly ash properties

- Fineness
  - strength
- Chemistry
  - Loss of workability
  - ASR
  - Time of setting
- Residual carbon
  - Air entraining



# Fineness drift example - PCCP

- Fly ash fineness drifts over a period of a few weeks
- Affect on construction
  - strength drift
  - Rejected lots
  - Replacement \$\$\$
- Specification weak on uniformity





# Concluding Remarks

- Standards have had a large positive effect on promoting durability
- Still important work to be done
- Contractors usually motivated by cost of construction
- Motivation must come from Users





© CTLGroup 2011. The information contained in this document is intended only for use by the individual or entity it was issued to. No part of this work may be disseminated, distributed, or reproduced in any form or by any graphic, electronic or mechanical means (including photocopying, photographing, taping, or retrieval systems) without the written permission of the author, CTLGroup, or its duly designated representatives.

BUILDING KNOWLEDGE. DELIVERING RESULTS.